
XBA-UAH8

XBA Option Switch Settings(Pulse/MDB/ICT104U/ICT104V) Supported bill H 5, 10, 20, 50, 100, 200, 500, 1000 8bills.

	FUNCTION	SW1	SW2	SW3	SW4	SW5	SW6	SW7	SW8
	Reject H 5 & 10	ON							
*	Accept H 5 & 10	OFF							
	Reject H 20		ON						
*	Accept H 20		OFF						
	Reject H 50			ON					
*	Accept H 50			OFF					
	Reject H 100 & 200				ON				
*	Accept H 100 & 200				OFF				
	Reject H 500 & 1000					ON			
*	Accept H 500 & 1000					OFF			
	Disable Bill Reject 4 Times BA Stop By 30 Sec					•	ON		
*	Enable Bill Reject 4 Times BA Stop By 30 Sec						OFF		
	Stack Banknote when Power-up							ON	
*	Reject Banknote when Power-up							OFF	
	Reserved								ON
*	Reserved							OFF	

This dip switch is located at the side of XBA.



Currency Assign Data


Interface Bill value	ICT104U	ICT104V	Pulse	MDB
BV1	H 5	H 5	H 5	H 5
BV2	H 10	H 10	H 10	H 10
BV3	H 20	H 20	H 20	H 20
BV4	H 50	H 50	H 50	H 50
BV5	H 100	H 100	H 100	H 100
BV6	H 200	H 200	H 200	H 200
BV7	H 500	H 500	H 500	H 500
BV8	H 1000	H 1000	H 1000	H 1000

Appendix

XBA-UAH8(Pulse/MDB/ICT104U/ICT104V)

	FUNCTION	SW1	SW2	SW3	SW4	SW5		SW6	SW7	SW8
	Inhibit Active HIGH	ON								
*	Inhibit Active LOW	OFF								
	Reserved		ON							
*	Reserved		OFF							
	Reserved			ON						
*	Reserved			OFF						
	Reserved				ON					
*	Reserved				OFF					
	Pulse Mode	MDB Mode				ICT104V Mode				
*	Credit-Pulse Normal HIGH	Scaling Factor (SF) = Decimal Point Position (DI				Connect with coin changer	ON			
	Credit-Pulse Normal LOW	Decimal Point Position (DP Scaling Factor (SF) = Decimal Point Position (DP				Connect with ICT VCCS converter board	OFF			
*	Pulse Mode							ON		
	Other Mode	OFF								
	Pulse Mode	Other Mode								
*	1 pulse / H 5	MDB Mode						OFF	OFF	
	5 pulse / H 5	Reserved						OFF	ON	
	10 pulse / H 5	ICT104U Mode							ON	OFF
	25 pulse / H 5 ICT104V Mode							ON	ON	

This dip switch is located on the CPU board, remove the CPU board cover first.



★ Manufacture setting

Affer setting dip switch of the credit pulses, you should reset the bill acceptor again.

Note: 1.Please reset the bill acceptor after set the dip switch.

2.Calibration card is needed.

© 2022 International Currency Technologies Corporation Vol. 1.0 Part Number : SWR8UA81000-R