

P85/P5 DIP SWITCHES SETTING: 1(Pulse/ccTalk)

Supported bill CZK 50, 100, 200, 500, 1000, 2000, 5000 7 bills.

<CZK 5000 is not taken by P85 Stacker>

	FUNCTION	SW1	SW2	SW3	SW4	SW5	SW6	SW7	SW8	SW9	SW10
*	1 Pulse / CZK 50	OFF	OFF	OFF							
	2 Pulse / CZK 50	OFF	OFF	ON							
	3 Pulse / CZK 50	OFF	ON	OFF							
	4 Pulse / CZK 50	OFF	ON	ON							
	5 Pulse / CZK 50	ON	OFF	OFF							
	10 Pulse / CZK 50	ON	OFF	ON							
	20 Pulse / CZK 50	ON	ON	OFF							
	100 Pulse / CZK 50	ON	ON	ON							
	Fast output Pulse Lo= 50ms Hi=100ms				ON						
*	Slow output Pulse Lo= 50ms Hi=300ms				OFF						
	Inhibit level Active Low					ON					
*	Inhibit level Active High					OFF					
*	Accept CZK 50 & 100						ON				
	Reject CZK 50 & 100						OFF				
*	Accept CZK 200 & 500							ON			
	Reject CZK 200 & 500							OFF			
*	Accept CZK 1000								ON		
	Reject CZK 1000								OFF		
*	Accept CZK 2000									ON	
	Reject CZK 2000									OFF	
*	Accept CZK 5000										ON
	Reject CZK 5000										OFF

★ Manufacture setting

Note: (1) Please reset the bill acceptor after set the dip switch.

(2) Dip switches 1 to 5 are only used for pulse protocol.

DIP SWITCHES SETTING: 2(Pulse)

	FUNCTION	SW1	SW2	SW3	SW4
*	Pulse Normal High	Pulse Normal High ON			
	Pulse Normal Low	OFF			
*	Pulse Mode	ON			
	ccTalk Interface		OFF		
	Reserved			ON	
*	Reserved			OFF	
	Ignore Sensor Problem(Note 1)				ON
*	Acknowledge Sensor Problem(Note 2)				OFF

★ Manufacture setting

Note:(1) Sensor 6 problem occurred ==>> BA will be still in working order.

(The face LED will be Flashing in short green about 2 seconds everytime you restart BA.)

(2) BA will stop to work when it acknowledges Sensor 6 problem occurred. (The face LED will be flashing in red.)

DIP SWITCHES SETTING: 2(ccTalk)

	FUNCTION		SW2	SW3	SW4	
*	Pulse Normal High	ON				
	Pulse Normal Low	OFF				
	Pulse Mode		ON			
*	ccTalk Interface		OFF			
	Please see Note (3) for detail			ON		
				OFF		
	Ignore Sensor Problem(Note 1)					
*	Acknowledge Sensor Problem(Note 2)				OFF	

★ Manufacture setting

Note:(1) Sensor 6 problem occurred ==>> BA will be still in working order.

(The face LED will be Flashing in short green about 2 seconds everytime you restart BA.)

- (2) BA will stop to work when it acknowledges Sensor 6 problem occurred. (The face LED will be flashing in red.)
- (3) ccTalk Parameters Reset

Put this switch to on and reset power will restore the ccTalk address to its default value of 40 and the encryption key to its default value of 123456.

*This has to be done after finished calibration process.