

Supported bill SK 20(93), 50(93), 100(93), 200(95, 99), 500(93, 00), 1000(93, 99), 5000(95, 99) 7bills.

	1000(33, 33), 3000(33, 33)										
	FUNCTION	SW1	SW2	SW3	SW4	SW5	SW6	SW7	SW8	SW9	SW10
*	1 Pulse / SK 10	OFF	OFF	OFF							
	2 Pulse / SK 10	OFF	OFF	ON							
	3 Pulse / SK 10	OFF	ON	OFF							
	4 Pulse / SK 10	OFF	ON	ON							
	5 Pulse / SK 10	ON	OFF	OFF							
	10 Pulse / SK 10	ON	OFF	ON							
	20 Pulse / SK 10	ON	ON	OFF							
	100 Pulse / SK 10	ON	ON	ON							
	Fast output Pulse Lo= 50ms Hi=100ms				ON						
*	Slow output Pulse Lo= 50ms Hi=300ms				OFF						
	Inhibit level Active Low					ON					
*	Inhibit level Active High					OFF					
*	Accept SK 20						ON				
	Reject SK 20						OFF				
*	Accept SK 50							ON			
	Reject SK 50							OFF			
*	Accept SK 100 & 200								ON		
	Reject SK 100 & 200								OFF		
*	Accept SK 500 & 1000									ON	
	Reject SK 500 & 1000									OFF	
*	Accept SK 5000										ON
	Reject SK 5000										OFF

★ Manufacture setting

Note: (1)Please reset the bill acceptor after set the dip switch.

(2)Dip switches 1 to 5 are only used for pulse protocol.

DIP SWITCHES SETTING: 2

	FUNCTION		SW2	sw3	SW4
-	Pulse Normal High				
	Pulse Normal Low	OFF			
	Pulse Protocol		ON		
	Parallel Protocol		OFF		
	HOLD			ОИ	
	HOLD			OFF	
	Ignore Sensor Problem(Note 1)			ON	
•	Acknowledge Sensor Problem (Note 2)		OFF		

★ Manufacture setting

Note: (1) Sensor 6 problem occurred ==>> BA will be still in working order.

(The face LED will be flashing in short green about 2 seconds everytime you restart BA.)

(2) BA will stop to work when it acknowledges Sensor 6 problem occurred.

(The face LED will be flashing in red.)